

## Ordering Examples

**S**


Single Clamp for Weld Mounting



Consists of:  
 2 HEX Bolts  
 1 COP Cover Plate  
 1 CLH Clamp Set (2 halves)  
 1 STW Weld Plate

**DS**


Double Clamp for Weld Mounting



Consists of:  
 4 HEX Bolts  
 2 COP Cover Plate  
 2 CLH Clamp Sets (4 halves)  
 1 DOW Weld Plate

**BS**

Clamp for Bolt Mounting



Consists of:  
 2 HEX Bolts  
 1 COP Cover Plate  
 1 CLH Clamp Set (2 halves)  
 1 BAP Weld Plate

**SSK**


Stacking Kit



Consists of:  
 2 STB Stacking Bolts  
 1 SAF Safety Plates  
 1 CLH Clamp Sets (2 halves)

**R0S**

Clamp for Rail-0 Mounting



Consists of:  
 2 HEX Bolts  
 1 COP Cover Plate  
 1 CLH Clamp Set (2 halves)  
 2 RCN-0 Rail Nuts  
 Standard material for the RCN-0 rail nuts is un-plated steel.

**R1S**


Clamp for Rail-1 Mounting



Consists of:  
 2 HEX Bolts  
 1 COP Cover Plate  
 1 CLH Clamp Set (2 halves)  
 2 RCN-1 Rail Nuts

**US**

Clamp for Strut Mounting



Consists of:  
 2 HEX Bolts  
 1 COP Cover Plate  
 1 CLH Clamp Set (2 halves)  
 2 UCN Strut Clips

**G\*S**

Clamp for Group Weld Mounting



Consists of:  
 2 HEX Bolts Per Position  
 1 COP Cover Plate Per Position  
 1 CLH Clamp Set Per Position  
 1 GRW Group Weld Plate (continuous)  
 Standard Material for GRW is un-plated steel.

\*is the number of positions  
 Example: Group 2, 5 positions of 1/2" Tube, PP Clamps, 304SS = G5ST2050-PP