

Ordering Examples

SH

Single Complete Clamp for Weld Mounting



Consists of:
 2 HEX Bolts
 1 SCP Cover Plate
 1 CLH Clamp Set (2 halves)
 1 SWP Weld Plate

DH

Double Complete Clamp for Weld Mounting



Consists of:
 4 HEX Bolts
 1 DCP Cover Plate
 2 CLH Clamp Sets (4 halves)
 1 DWP Double Weld Plate

**R7H
R8H**


Single Complete Clamp for Rail Mounting



Consists of:
 2 HEX Bolts
 1 SCP Cover Plate
 1 CLH Clamp Set (2 halves)
 2 RCN Rail Nuts

R9H

Single Complete Clamp for Rail Mounting
Group H7 Only



Consists of:
 2 HEX Bolts
 1 SCP Cover Plate
 1 CLH Clamp Set (2 halves)
 1 SPL Spacer Plate
 2 RCN-9 Rail Nuts

HSK


Complete Stacking Kit



Consists of:
 2 STB Stacking Bolts
 1 SAF Safety Plate
 1 CLH Clamp Set (2 halves)

UH

Single Complete Clamp for Strut Mounting



Consists of:
 2 HEX Bolts
 1 SCP Cover Plate
 1 CLH Clamp Set (2 halves)
 2 UCN Strut Nuts